

STEP 3

 Franmar

TIP SHEET

D•HAZE®

# HAZE REMOVER

Screen Ghost and Haze Remover

*Made with Soybeans • 100% Biodegradable • Non-Toxic and Non-Caustic*

**Franmar's Haze Remover** is one of the safest and most effective ghost and haze removers in the industry today! Unlike traditional caustic haze removers, **Franmar's Haze Remover** will not damage screen mesh no matter how long you leave it on. Good haze removal practices save screen printers money, with longer usability of screens.

## Directions

- 1 Spray or pour a minimal amount onto screen haze/ghost image.
- 2 Scrub both sides of screen with dedicated Biggee™ pad or nylon brush.
- 3 Rinse screen clean with pressured water.

## Usage Tips

- Use each time immediately after removal of stencil removal or ghosting will not set in the screen.
- Control amount by using a spray bottle; washing frame pieces as Haze Remover will remove the glue holding the mesh to the frame.
- Use Franmar's Screen Degreaser to remove any residue.

*Chat with a live customer service rep (No phone menu maze!)*

**800-538-5069**

7am - 5:30pm Mon - Thurs. Friday 7am - 5:00pm CT

or visit our website: [www.franmar.com](http://www.franmar.com)

 Franmar®

rev. 6/15/2015