

STEP 1



TIP SHEET

UV INK REMOVER

Cleans Screens Safely and Easily

Made with Soybeans • 100% Biodegradable • Non-Toxic and Non-Caustic

Today industrial printers are moving to more earth friendly inks such as UV. Franmar offers the perfect cleaner for these UV inks. **Franmar's UV INK REMOVER** is a great cleaner that is low odor, 100% biodegradable, and easily degrades UV ink from screen meshes.

Directions

- 1 Spray or pour a small amount onto screen.
- 2 Scrub screen with a shop towel, dedicated Biggee™ pad, or nylon brush.
- 3 Repeat on back of screen image.
- 4 Clean both sides of screen with a shop towel or pressured water.

Usage Tips

- Use a flip-top cap for more controlled application.
- A standard size screen generally needs only 6-7 sprays of product.
- Franmar's Screen Degreaser helps with clean-up.

Chat with a live customer service rep (No phone menu maze!)

800-538-5069

7am - 5:30pm Mon - Thurs. Friday 7am - 5:00pm CT

or visit our website: www.franmar.com



rev. 6/15/2015