

STEP 3**TIP SHEET**

Screen ghost and haze remover

D•HAZE®

Haze Remover



Franmar's **D•HAZE® Haze Remover** is one of the most effective ghost and haze removers in the industry today. Unlike traditional caustic haze removers, Franmar's **D•HAZE** will not damage screen mesh - no matter how long you leave it on. Good haze removal practices save screen printers money with longer usability of screens.

Directions:

1. Spray or pour a small amount on screen haze/ghost image.
2. Scrub both sides of screen with a dedicated Biggee™ scrub pad or nylon brush.
3. Rinse screen clean with pressured water.

Usage Tips:

- Use immediately after emulsion or stencil removal so ghost/haze will not set in the screen.
- Control amount by using a spray bottle, avoiding frame edges as D•HAZE will remove the glue holding the mesh to the frame.
- Use Franmar's D•GREASE™ Screen Degreaser to remove any residue.

MORE INFORMATION:

Precautions: Dispose of waste according to local regulations. Avoid eye contact. If product contacts eye, rinse thoroughly with water. Call a physician if irritation persists. If swallowed do not induce vomiting. Call a physician. Use of gloves made of butyl rubber or laminated polyethylene/EVOH is recommended.

WARNING: This product can expose you to chemicals including n-methyl-2-pyrrolidone, which is known to the state of California to cause birth defects or other reproductive harm. For more information, go to www.P65Warnings.ca.gov.



Chat with a live customer service rep:

800-538-5069

8:00am - 5:00pm CST Monday - Friday

or visit our website: www.franmar.com

rev. 3/30/2023